

五常國小飲水機維護紀錄表													
編號	安裝位置	型 號	區別	濾心規格	濾心更換	機器巡檢	水質檢驗	加熱系統	冷卻系統	殺菌系統	外觀清潔	給排水系統	維護紀錄
1	明德2F會議室	UR-313AS1	A-1			✓	✓	✓	✓	✓	✓	✓	✓
2	明德2F會計室	UR-313AS1	A-2			✓	✓	✓	✓	✓	✓	✓	✓
3	明德3F圖書館	UR-313AS1	A-3			✓	✓	✓	✓	✓	✓	✓	✓
4	活動中心5F	UR-313AS1	A-4			✓	✓	✓	✓	✓	✓	✓	✓
5	明德1F電梯旁	UR-313AS1	B-1			✓	✓	✓	✓	✓	✓	✓	✓
6	明德1F車道旁	UR-313AS1	B-2			✓	✓	✓	✓	✓	✓	✓	✓
7	快樂1F西後門	UR-313AS1	B-3			✓	✓	✓	✓	✓	✓	✓	✓
8	1F廚房	UW-9615	B-4			✓	✓	✓	✓	✓	✓	✓	✓
9	銀 河 班	UW-9213	C-1			✓	✓	✓	✓	✓	✓	✓	✓
10	白 雲 班	UW-9213	C-2			✓	✓	✓	✓	✓	✓	✓	✓
11	月 亮 班	UW-9213	C-3			✓	✓	✓	✓	✓	✓	✓	✓
12	綠 地 班	UW-9203	C-4			✓	✓	✓	✓	✓	✓	✓	✓
13	幼稚園健康中心	UW-20000A	C-5			✓	✓	✓	✓	✓	✓	✓	✓
14	快樂2F	UW-9615	C-6			✓	✓	✓	✓	✓	✓	✓	✓
15	勤學1F西側樓梯	UR-313AS1	D-1			✓	✓	✓	✓	✓	✓	✓	✓
16	勤學2F西側樓梯	UR-313AS1	D-2			✓	✓	✓	✓	✓	✓	✓	✓
17	勤學3F西側樓梯	UR-313AS1	D-3			✓	✓	✓	✓	✓	✓	✓	✓
18	勤學4F西側樓梯	UR-313AS1	D-4			✓	✓	✓	✓	✓	✓	✓	✓
19	勤學4F東側樓梯	UR-313AS1	E-1			✓	✓	✓	✓	✓	✓	✓	✓
20	勤學2F東側樓梯	UR-313AS1	E-2			✓	✓	✓	✓	✓	✓	✓	✓
21	勤學3F東側樓梯	UW-313AS1	E-3			✓	✓	✓	✓	✓	✓	✓	✓
22	勤學4F東側樓梯	UR-313AS1	E-4			✓	✓	✓	✓	✓	✓	✓	✓
23	健康1F西側廁所	UW-998	F-1			✓	✓	✓	✓	✓	✓	✓	✓
24	健康2F西側廁所	UR-313AS1	F-2			✓	✓	✓	✓	✓	✓	✓	✓
25	健康2F東側	UR-313AS1	F-3			✓	✓	✓	✓	✓	✓	✓	✓
26	健康1F東側	UR-313AS1	F-4			✓	✓	✓	✓	✓	✓	✓	✓
27	健康2F女廁	UR-313AS1	G-1			✓	✓	✓	✓	✓	✓	✓	✓
28	健康3F女廁	UR-313AS1	G-2			✓	✓	✓	✓	✓	✓	✓	✓
29	健康3F西側	UR-313AS1	G-3			✓	✓	✓	✓	✓	✓	✓	✓
30	健康3F東側	UR-313AS1	G-4			✓	✓	✓	✓	✓	✓	✓	✓
日期：109年1月3日													

機台巡檢數量：30 台

服務員：

郭有福

客戶簽章：

事務長 閔麗芬

五常國小飲水機維護紀錄表

編號	安裝位置	型號	區別	濾心規格	濾心更換	機器巡檢	水質檢驗	加熱系統	冷卻系統	殺菌系統	外觀清潔	給排水系統	維護紀錄
1	明德2F會議室	UR-313AS1	A-1			✓	✓	✓	✓	✓	✓	✓	
2	明德2F會計室	UR-313AS1	A-2			✓	✓	✓	✓	✓	✓	✓	
3	明德3F圖書館	UR-313AS1	A-3			✓	✓	✓	✓	✓	✓	✓	
4	活動中心5F	UR-313AS1	A-4			✓	✓	✓	✓	✓	✓	✓	
5	明德1F電梯旁	UR-313AS1	B-1			✓	✓	✓	✓	✓	✓	✓	
6	明德1F車道旁	UR-313AS1	B-2			✓	✓	✓	✓	✓	✓	✓	
7	快樂1F西後門	UR-313AS1	B-3			✓	✓	✓	✓	✓	✓	✓	
8	1F廚房	UW-9615	B-4			✓	✓	✓	✓	✓	✓	✓	
9	銀河班	UW-9213	C-1			✓	✓	✓	✓	✓	✓	✓	
10	白雲班	UW-9213	C-2			✓	✓	✓	✓	✓	✓	✓	
11	月亮班	UW-9213	C-3			✓	✓	✓	✓	✓	✓	✓	
12	綠地班	UW-9203	C-4			✓	✓	✓	✓	✓	✓	✓	
13	幼稚園健康中心	UW-20000A	C-5			✓	✓	✓	✓	✓	✓	✓	
14	快樂2F	UW-9615	C-6			✓	✓	✓	✓	✓	✓	✓	
15	勤學1F西側樓梯	UR-313AS1	D-1			✓	✓	✓	✓	✓	✓	✓	
16	勤學2F西側樓梯	UR-313AS1	D-2			✓	✓	✓	✓	✓	✓	✓	
17	勤學3F西側樓梯	UR-313AS1	D-3			✓	✓	✓	✓	✓	✓	✓	
18	勤學4F西側樓梯	UR-313AS1	D-4			✓	✓	✓	✓	✓	✓	✓	
19	勤學4F東側樓梯	UR-313AS1	E-1			✓	✓	✓	✓	✓	✓	✓	
20	勤學2F東側樓梯	UR-313AS1	E-2			✓	✓	✓	✓	✓	✓	✓	
21	勤學3F東側樓梯	UW-313AS1	E-3			✓	✓	✓	✓	✓	✓	✓	
22	勤學4F東側樓梯	UR-313AS1	E-4			✓	✓	✓	✓	✓	✓	✓	
23	健康1F西側廁所	UW-998	F-1			✓	✓	✓	✓	✓	✓	✓	
24	健康2F西側廁所	UR-313AS1	F-2			✓	✓	✓	✓	✓	✓	✓	
25	健康2F東側	UR-313AS1	F-3			✓	✓	✓	✓	✓	✓	✓	
26	健康1F東側	UR-313AS1	F-4			✓	✓	✓	✓	✓	✓	✓	
27	健康2F女廁	UR-313AS1	G-1			✓	✓	✓	✓	✓	✓	✓	
28	健康3F女廁	UR-313AS1	G-2			✓	✓	✓	✓	✓	✓	✓	
29	健康3F西側	UR-313AS1	G-3			✓	✓	✓	✓	✓	✓	✓	
30	健康3F東側	UR-313AS1	G-4			✓	✓	✓	✓	✓	✓	✓	
日期：109年2月3日													

機台巡檢數量：30 台

服務員：楊祐帆

客戶簽章：



五常國小飲水機維護紀錄表

編號	安裝位置	型號	區別	濾心規格	濾心更換	機器巡檢	水質檢驗	加熱系統	冷卻系統	殺菌系統	外觀清潔	給排水系統	維護紀錄
1	明德2F會議室	UR-313AS1	A-1	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
2	明德2F會計室	UR-313AS1	A-2	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
3	明德3F圖書館	UR-313AS1	A-3	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
4	活動中心5F	UR-313AS1	A-4	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
5	明德1F電梯旁	UR-313AS1	B-1	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
6	明德1F車道旁	UR-313AS1	B-2	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
7	快樂1F後門	UR-313AS1	B-3	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
8	1F廚房	UW-9615	B-4	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
9	銀河班	UW-9213	C-1	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
10	白雲班	UW-9213	C-2	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
11	月亮班	UW-9213	C-3	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
12	綠地班	UW-9203	C-4	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
13	幼稚園健康中心	UW-20000A	C-5	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
14	快樂2F	UW-9615	C-6	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
15	勤學1F西側樓梯	UR-313AS1	D-1	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
16	勤學2F西側樓梯	UR-313AS1	D-2	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
17	勤學3F西側樓梯	UR-313AS1	D-3	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
18	勤學4F西側樓梯	UR-313AS1	D-4	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
19	勤學4F東側樓梯	UR-313AS1	E-1	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
20	勤學2F東側樓梯	UR-313AS1	E-2	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
21	勤學3F東側樓梯	UW-313AS1	E-3	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
22	勤學4F東側樓梯	UR-313AS1	E-4	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
23	健康1F西側廁所	UW-998	F-1	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
24	健康2F西側廁所	UR-313AS1	F-2	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
25	健康2F東側	UR-313AS1	F-3	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
26	健康1F東側	UR-313AS1	F-4	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
27	健康2F女廁	UR-313AS1	G-1	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
28	健康3F女廁	UR-313AS1	G-2	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
29	健康3F西側	UR-313AS1	G-3	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
30	健康3F東側	UR-313AS1	G-4	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
日期：104年3月5日					✓	✓	✓	✓	✓	✓	✓	✓	✓

機台巡檢數量：30 台

服務員：

郭有福

客戶簽章：

事務組長 關麗芬

五常國小飲水機維護紀錄表

編號	安裝位置	型號	區別	濾心規格	濾心更換	機器巡檢	水質檢驗	加熱系統	冷卻系統	殺菌系統	外觀清潔	給排水系統	維護紀錄
1	明德2F會議室	UR-313AS1	A-1			✓	✓	✓	✓	✓	✓	✓	
2	明德2F會計室	UR-313AS1	A-2			✓	✓	✓	✓	✓	✓	✓	
3	明德3F圖書館	UR-313AS1	A-3			✓	✓	✓	✓	✓	✓	✓	
4	活動中心5F	UR-313AS1	A-4			✓	✓	✓	✓	✓	✓	✓	
5	明德1F電梯旁	UR-313AS1	B-1			✓	✓	✓	✓	✓	✓	✓	
6	明德1F車道旁	UR-313AS1	B-2			✓	✓	✓	✓	✓	✓	✓	
7	快樂1F西後門	UR-313AS1	B-3			✓	✓	✓	✓	✓	✓	✓	
8	1F廚房	UW-9615	B-4			✓	✓	✓	✓	✓	✓	✓	
9	銀河班	UW-9213	C-1			✓	✓	✓	✓	✓	✓	✓	
10	白雲班	UW-9213	C-2			✓	✓	✓	✓	✓	✓	✓	
11	月亮班	UW-9213	C-3			✓	✓	✓	✓	✓	✓	✓	
12	綠地班	UW-9203	C-4			✓	✓	✓	✓	✓	✓	✓	
13	幼稚園健康中心	UW-20000A	C-5			✓	✓	✓	✓	✓	✓	✓	
14	快樂2F	UW-9615	C-6			✓	✓	✓	✓	✓	✓	✓	
15	勤學1F西側樓梯	UR-313AS1	D-1			✓	✓	✓	✓	✓	✓	✓	
16	勤學2F西側樓梯	UR-313AS1	D-2			✓	✓	✓	✓	✓	✓	✓	
17	勤學3F西側樓梯	UR-313AS1	D-3			✓	✓	✓	✓	✓	✓	✓	
18	勤學4F西側樓梯	UR-313AS1	D-4			✓	✓	✓	✓	✓	✓	✓	
19	勤學4F東側樓梯	UR-313AS1	E-1			✓	✓	✓	✓	✓	✓	✓	
20	勤學2F東側樓梯	UR-313AS1	E-2			✓	✓	✓	✓	✓	✓	✓	
21	勤學3F東側樓梯	UW-313AS1	E-3			✓	✓	✓	✓	✓	✓	✓	
22	勤學4F東側樓梯	UR-313AS1	E-4			✓	✓	✓	✓	✓	✓	✓	
23	健康1F西側廁所	UW-998	F-1			✓	✓	✓	✓	✓	✓	✓	
24	健康2F西側廁所	UR-313AS1	F-2			✓	✓	✓	✓	✓	✓	✓	
25	健康2F東側	UR-313AS1	F-3			✓	✓	✓	✓	✓	✓	✓	
26	健康1F東側	UR-313AS1	F-4			✓	✓	✓	✓	✓	✓	✓	
27	健康2F女廁	UR-313AS1	G-1			✓	✓	✓	✓	✓	✓	✓	
28	健康3F女廁	UR-313AS1	G-2			✓	✓	✓	✓	✓	✓	✓	
29	健康3F西側	UR-313AS1	G-3			✓	✓	✓	✓	✓	✓	✓	
30	健康3F東側	UR-313AS1	G-4			✓	✓	✓	✓	✓	✓	✓	
日期: 107年4月6日													

機台巡檢數量: 30 台

服務員:

楊祐帆

客戶簽章:

事務 關麗芬

五常國小飲水機維護紀錄表

編號	安裝位置	型號	區別	濾心規格	濾心更換	機器巡檢	水質檢驗	加熱系統	冷卻系統	殺菌系統	外觀清潔	給排水系統	維護紀錄
1	明德2F會議室	UR-313AS1	A-1			✓	✓	✓	✓	✓	✓	✓	
2	明德2F會計室	UR-313AS1	A-2			✓	✓	✓	✓	✓	✓	✓	
3	明德3F圖書館	UR-313AS1	A-3			✓	✓	✓	✓	✓	✓	✓	
4	活動中心5F	UR-313AS1	A-4			✓	✓	✓	✓	✓	✓	✓	
5	明德1F電梯旁	UR-313AS1	B-1			✓	✓	✓	✓	✓	✓	✓	
6	明德1F車道旁	UR-313AS1	B-2			✓	✓	✓	✓	✓	✓	✓	
7	快樂1F西後門	UR-313AS1	B-3			✓	✓	✓	✓	✓	✓	✓	
8	1F廚房	UW-9615	B-4			✓	✓	✓	✓	✓	✓	✓	
9	銀河班	UW-9213	C-1			✓	✓	✓	✓	✓	✓	✓	
10	白雲班	UW-9213	C-2			✓	✓	✓	✓	✓	✓	✓	
11	月亮班	UW-9213	C-3			✓	✓	✓	✓	✓	✓	✓	
12	綠地班	UW-9203	C-4			✓	✓	✓	✓	✓	✓	✓	
13	幼稚園健康中心	UW-20000A	C-5			✓	✓	✓	✓	✓	✓	✓	
14	快樂2F	UW-9615	C-6			✓	✓	✓	✓	✓	✓	✓	
15	勤學1F西側樓梯	UR-313AS1	D-1			✓	✓	✓	✓	✓	✓	✓	
16	勤學2F西側樓梯	UR-313AS1	D-2			✓	✓	✓	✓	✓	✓	✓	
17	勤學3F西側樓梯	UR-313AS1	D-3			✓	✓	✓	✓	✓	✓	✓	
18	勤學4F西側樓梯	UR-313AS1	D-4			✓	✓	✓	✓	✓	✓	✓	
19	勤學1F東側樓梯	UR-313AS1	E-1			✓	✓	✓	✓	✓	✓	✓	
20	勤學2F東側樓梯	UR-313AS1	E-2			✓	✓	✓	✓	✓	✓	✓	
21	勤學3F東側樓梯	UW-9615	E-3			✓	✓	✓	✓	✓	✓	✓	
22	勤學4F東側樓梯	UR-313AS1	E-4			✓	✓	✓	✓	✓	✓	✓	
23	健康1F西側廁所	UW-998	F-1			✓	✓	✓	✓	✓	✓	✓	
24	健康2F西側廁所	UR-313AS1	F-2			✓	✓	✓	✓	✓	✓	✓	
25	健康2F東側	UR-313AS1	F-3			✓	✓	✓	✓	✓	✓	✓	
26	健康1F東側	UR-313AS1	F-4			✓	✓	✓	✓	✓	✓	✓	
27	健康2F女廁	UR-313AS1	G-1			✓	✓	✓	✓	✓	✓	✓	
28	健康3F女廁	UR-313AS1	G-2			✓	✓	✓	✓	✓	✓	✓	
29	健康3F西側	UR-313AS1	G-3			✓	✓	✓	✓	✓	✓	✓	
30	健康3F東側	UR-313AS1	G-4			✓	✓	✓	✓	✓	✓	✓	
日期：109年5月6日													

機台巡檢數量：30 台

服務員：

楊祐帆

客戶簽章：

事務組 龔麗芬

五常國小飲水機維護紀錄表

編號	安裝位置	型號	區別	濾心規格	濾心更換	機器巡檢	水質檢驗	加熱系統	冷卻系統	殺菌系統	外觀清潔	給排水系統	維護紀錄
1	明德2F會議室	UR-313AS1	A-1	6164	✓	✓	✓	✓	✓	✓	✓	✓	
2	明德2F會計室	UR-313AS1	A-2	6164	✓	✓	✓	✓	✓	✓	✓	✓	
3	明德3F圖書館	UR-313AS1	A-3	6164	✓	✓	✓	✓	✓	✓	✓	✓	
4	活動中心5F	UR-313AS1	A-4	6164	✓	✓	✓	✓	✓	✓	✓	✓	
5	明德1F電梯旁	UR-313AS1	B-1	6164	✓	✓	✓	✓	✓	✓	✓	✓	
6	明德1F車道旁	UR-313AS1	B-2	6164	✓	✓	✓	✓	✓	✓	✓	✓	
7	快樂1F西後門	UR-313AS1	B-3	6164	✓	✓	✓	✓	✓	✓	✓	✓	
8	1F廚房	UW-9615	B-4	6164	✓	✓	✓	✓	✓	✓	✓	✓	
9	銀河班	UW-9213	C-1	6164	✓	✓	✓	✓	✓	✓	✓	✓	
10	白雲班	UW-9213	C-2	6164	✓	✓	✓	✓	✓	✓	✓	✓	
11	月亮班	UW-9213	C-3	6164	✓	✓	✓	✓	✓	✓	✓	✓	
12	綠地班	UW-9203	C-4	6164	✓	✓	✓	✓	✓	✓	✓	✓	
13	幼稚園健康中心	UW-20000A	C-5	6164	✓	✓	✓	✓	✓	✓	✓	✓	
14	快樂2F	UW-9615	C-6	6164	✓	✓	✓	✓	✓	✓	✓	✓	
15	勤學1F西側樓梯	UR-313AS1	D-1	6164	✓	✓	✓	✓	✓	✓	✓	✓	
16	勤學2F西側樓梯	UR-313AS1	D-2	6164	✓	✓	✓	✓	✓	✓	✓	✓	
17	勤學3F西側樓梯	UR-313AS1	D-3	6164	✓	✓	✓	✓	✓	✓	✓	✓	
18	勤學4F西側樓梯	UR-313AS1	D-4	6164	✓	✓	✓	✓	✓	✓	✓	✓	
19	勤學1F東側樓梯	UR-313AS1	E-1	6164	✓	✓	✓	✓	✓	✓	✓	✓	
20	勤學2F東側樓梯	UR-313AS1	E-2	6164	✓	✓	✓	✓	✓	✓	✓	✓	
21	勤學3F東側樓梯	UW-313AS1	E-3	6164	✓	✓	✓	✓	✓	✓	✓	✓	
22	勤學4F東側樓梯	UR-313AS1	E-4	6164	✓	✓	✓	✓	✓	✓	✓	✓	
23	健康1F西側廁所	UW-998	F-1	6164	✓	✓	✓	✓	✓	✓	✓	✓	
24	健康2F西側廁所	UR-313AS1	F-2	6164	✓	✓	✓	✓	✓	✓	✓	✓	
25	健康2F東側	UR-313AS1	F-3	6164	✓	✓	✓	✓	✓	✓	✓	✓	
26	健康1F東側	UR-313AS1	F-4	6164	✓	✓	✓	✓	✓	✓	✓	✓	
27	健康2F女廁	UR-313AS1	G-1	6164	✓	✓	✓	✓	✓	✓	✓	✓	
28	健康3F女廁	UR-313AS1	G-2	6164	✓	✓	✓	✓	✓	✓	✓	✓	
29	健康3F西側	UR-313AS1	G-3	6164	✓	✓	✓	✓	✓	✓	✓	✓	
30	健康3F東側	UR-313AS1	G-4	6164	✓	✓	✓	✓	✓	✓	✓	✓	
日期：109年6月1日													

機台巡檢數量：30 台

服務員：楊祐中

客戶簽章：



五常國小飲水機維護紀錄表													
編號	安裝位置	型 號	區別	濾心規格	濾心更換	機器巡檢	水質檢驗	加熱系統	冷卻系統	殺菌系統	外觀清潔	給排水系統	維護紀錄
1	明德2F會議室	UR-313AS1	A-1			✓	✓	✓	✓	✓	✓	✓	
2	明德2F會計室	UR-313AS1	A-2			✓	✓	✓	✓	✓	✓	✓	
3	明德3F圖書館	UR-313AS1	A-3			✓	✓	✓	✓	✓	✓	✓	
4	活動中心5F	UR-313AS1	A-4			✓	✓	✓	✓	✓	✓	✓	
5	明德1F電梯旁	UR-313AS1	B-1			✓	✓	✓	✓	✓	✓	✓	
6	明德1F車道旁	UR-313AS1	B-2			✓	✓	✓	✓	✓	✓	✓	
7	快樂1F西後門	UR-313AS1	B-3			✓	✓	✓	✓	✓	✓	✓	
8	1F廚房	UW-9615	B-4			✓	✓	✓	✓	✓	✓	✓	
9	銀 河 班	UW-9213	C-1			✓	✓	✓	✓	✓	✓	✓	
10	白 雲 班	UW-9213	C-2			✓	✓	✓	✓	✓	✓	✓	
11	月 亮 班	UW-9213	C-3			✓	✓	✓	✓	✓	✓	✓	
12	綠 地 班	UW-9203	C-4			✓	✓	✓	✓	✓	✓	✓	
13	幼稚園健康中心	UW-20000A	C-5			✓	✓	✓	✓	✓	✓	✓	
14	快樂2F	UW-9615	C-6			✓	✓	✓	✓	✓	✓	✓	
15	勤學1F西側樓梯	UR-313AS1	D-1			✓	✓	✓	✓	✓	✓	✓	
16	勤學2F西側樓梯	UR-313AS1	D-2			✓	✓	✓	✓	✓	✓	✓	
17	勤學3F西側樓梯	UR-313AS1	D-3			✓	✓	✓	✓	✓	✓	✓	
18	勤學4F西側樓梯	UR-313AS1	D-4			✓	✓	✓	✓	✓	✓	✓	
19	勤學1F東側樓梯	UR-313AS1	E-1			✓	✓	✓	✓	✓	✓	✓	
20	勤學2F東側樓梯	UR-313AS1	E-2			✓	✓	✓	✓	✓	✓	✓	
21	勤學3F東側樓梯	UW-9615	E-3			✓	✓	✓	✓	✓	✓	✓	
22	勤學4F東側樓梯	UR-313AS1	E-4			✓	✓	✓	✓	✓	✓	✓	
23	健康1F西側廁所	UW-998	F-1			✓	✓	✓	✓	✓	✓	✓	
24	健康2F西側廁所	UR-313AS1	F-2			✓	✓	✓	✓	✓	✓	✓	
25	健康2F東側	UR-313AS1	F-3			✓	✓	✓	✓	✓	✓	✓	
26	健康1F東側	UR-313AS1	F-4			✓	✓	✓	✓	✓	✓	✓	
27	健康2F女廁	UR-313AS1	G-1			✓	✓	✓	✓	✓	✓	✓	
28	健康3F女廁	UR-313AS1	G-2			✓	✓	✓	✓	✓	✓	✓	
29	健康3F西側	UR-313AS1	G-3			✓	✓	✓	✓	✓	✓	✓	
30	健康3F東側	UR-313AS1	G-4			✓	✓	✓	✓	✓	✓	✓	
日期：109年 7 月 1 日													

機台巡檢數量： 30 台

服務員：

楊祐凱

客戶簽章：

事務組長 關麗芬

五常國小飲水機維護紀錄表													
編號	安裝位置	型 號	區別	濾心規格	濾心更換	機器巡檢	水質檢驗	加熱系統	冷卻系統	殺菌系統	外觀清潔	給排水系統	維護紀錄
1	明德2F會議室	UR-313AS1	A-1			✓	✓	✓	✓	✓	✓	✓	
2	明德2F會計室	UR-313AS1	A-2			✓	✓	✓	✓	✓	✓	✓	
3	明德3F圖書館	UR-313AS1	A-3			✓	✓	✓	✓	✓	✓	✓	
4	活動中心5F	UR-313AS1	A-4			✓	✓	✓	✓	✓	✓	✓	
5	明德1F電梯旁	UR-313AS1	B-1			✓	✓	✓	✓	✓	✓	✓	
6	明德1F車道旁	UR-313AS1	B-2			✓	✓	✓	✓	✓	✓	✓	
7	快樂1F西後門	UR-313AS1	B-3			✓	✓	✓	✓	✓	✓	✓	
8	1F廚房	UW-9615	B-4			✓	✓	✓	✓	✓	✓	✓	
9	銀 河 班	UW-9213	C-1			✓	✓	✓	✓	✓	✓	✓	
10	白 雲 班	UW-9213	C-2			✓	✓	✓	✓	✓	✓	✓	
11	月 亮 班	UW-9213	C-3			✓	✓	✓	✓	✓	✓	✓	
12	綠 地 班	UW-9203	C-4			✓	✓	✓	✓	✓	✓	✓	
13	幼稚園健康中心	UW-20000A	C-5			✓	✓	✓	✓	✓	✓	✓	
14	快樂2F	UW-9615	C-6			✓	✓	✓	✓	✓	✓	✓	
15	勤學1F西側樓梯	UR-313AS1	D-1			✓	✓	✓	✓	✓	✓	✓	
16	勤學2F西側樓梯	UR-313AS1	D-2			✓	✓	✓	✓	✓	✓	✓	
17	勤學3F西側樓梯	UR-313AS1	D-3			✓	✓	✓	✓	✓	✓	✓	
18	勤學4F西側樓梯	UR-313AS1	D-4			✓	✓	✓	✓	✓	✓	✓	
19	勤學1F東側樓梯	UR-313AS1	E-1			✓	✓	✓	✓	✓	✓	✓	
20	勤學2F東側樓梯	UR-313AS1	E-2			✓	✓	✓	✓	✓	✓	✓	
21	勤學3F東側樓梯	UW-9615	E-3			✓	✓	✓	✓	✓	✓	✓	
22	勤學4F東側樓梯	UR-313AS1	E-4			✓	✓	✓	✓	✓	✓	✓	
23	健康1F西側廁所	UW-998	F-1			✓	✓	✓	✓	✓	✓	✓	
24	健康2F西側廁所	UR-313AS1	F-2			✓	✓	✓	✓	✓	✓	✓	
25	健康2F東側	UR-313AS1	F-3			✓	✓	✓	✓	✓	✓	✓	
26	健康1F東側	UR-313AS1	F-4			✓	✓	✓	✓	✓	✓	✓	
27	健康2F女廁	UR-313AS1	G-1			✓	✓	✓	✓	✓	✓	✓	
28	健康3F女廁	UR-313AS1	G-2			✓	✓	✓	✓	✓	✓	✓	
29	健康3F西側	UR-313AS1	G-3			✓	✓	✓	✓	✓	✓	✓	
30	健康3F東側	UR-313AS1	G-4			✓	✓	✓	✓	✓	✓	✓	
日期：109年8月24日													

機台巡檢數量：30 台

服務員：周秋奇

客戶簽章：蓋章區

五常國小飲水機維護紀錄表													
編號	安裝位置	型 號	區別	濾心規格	濾心更換	機器巡檢	水質檢驗	加熱系統	冷卻系統	殺菌系統	外觀清潔	給排水系統	維護紀錄
1	明德2F會議室	UR-313AS1	A-1			✓	✓	✓	✓	✓	✓	✓	
2	明德2F會計室	UR-313AS1	A-2			✓	✓	✓	✓	✓	✓	✓	
3	明德3F圖書館	UR-313AS1	A-3		✓	✓	✓	✓	✓	✓	✓	✓	
4	活動中心5F	UR-313AS1	A-4		✓	✓	✓	✓	✓	✓	✓	✓	
5	明德1F電梯旁	UR-313AS1	B-1			✓	✓	✓	✓	✓	✓	✓	
6	明德1F車道旁	UR-313AS1	B-2			✓	✓	✓	✓	✓	✓	✓	
7	快樂1F西後門	UR-313AS1	B-3		✓	✓	✓	✓	✓	✓	✓	✓	
8	1F廚房	UW-9615	B-4		✓	✓	✓	✓	✓	✓	✓	✓	
9	銀 河 班	UW-9213	C-1			✓	✓	✓	✓	✓	✓	✓	
10	白 雲 班	UW-9213	C-2			✓	✓	✓	✓	✓	✓	✓	
11	月 亮 班	UW-9213	C-3			✓	✓	✓	✓	✓	✓	✓	
12	綠 地 班	UW-9203	C-4			✓	✓	✓	✓	✓	✓	✓	
13	幼稚園健康中心	UW-20000A	C-5		✓	✓	✓	✓	✓	✓	✓	✓	
14	快樂2F	UW-9615	C-6		✓	✓	✓	✓	✓	✓	✓	✓	
15	勤學1F西側樓梯	UR-313AS1	D-1			✓	✓	✓	✓	✓	✓	✓	
16	勤學2F西側樓梯	UR-313AS1	D-2			✓	✓	✓	✓	✓	✓	✓	
17	勤學3F西側樓梯	UR-313AS1	D-3			✓	✓	✓	✓	✓	✓	✓	
18	勤學4F西側樓梯	UR-313AS1	D-4			✓	✓	✓	✓	✓	✓	✓	
19	勤學1F東側樓梯	UR-313AS1	E-1			✓	✓	✓	✓	✓	✓	✓	
20	勤學2F東側樓梯	UR-313AS1	E-2			✓	✓	✓	✓	✓	✓	✓	
21	勤學3F東側樓梯	UW-9615	E-3		✓	✓	✓	✓	✓	✓	✓	✓	
22	勤學4F東側樓梯	UR-313AS1	E-4			✓	✓	✓	✓	✓	✓	✓	
23	健康1F西側廁所	UW-998	F-1		✓	✓	✓	✓	✓	✓	✓	✓	
24	健康2F西側廁所	UR-313AS1	F-2			✓	✓	✓	✓	✓	✓	✓	
25	健康2F東側	UR-313AS1	F-3			✓	✓	✓	✓	✓	✓	✓	
26	健康1F東側	UR-313AS1	F-4			✓	✓	✓	✓	✓	✓	✓	
27	健康2F女廁	UR-313AS1	G-1			✓	✓	✓	✓	✓	✓	✓	
28	健康3F女廁	UR-313AS1	G-2		✓	✓	✓	✓	✓	✓	✓	✓	
29	健康3F西側	UR-313AS1	G-3		✓	✓	✓	✓	✓	✓	✓	✓	
30	健康3F東側	UR-313AS1	G-4		✓	✓	✓	✓	✓	✓	✓	✓	
日期：109年9月 日													

機台巡檢數量：30 台

換濾心 11 台

服務員：周秋奇

客戶簽章：廖麗芬

五常國小飲水機維護紀錄表													
編號	安裝位置	型號	區別	濾心規格	濾心更換	機器巡檢	水質檢驗	加熱系統	冷卻系統	殺菌系統	外觀清潔	給排水系統	維護紀錄
1	明德2F會議室		A-1			✓		✓	✓	✓	✓	✓	✓
2	明德2F會計室		A-2			✓		✓	✓	✓	✓	✓	✓
3	明德3F圖書館		A-3			✓		✓	✓	✓	✓	✓	✓
4	活動中心5F		A-4			✓		✓	✓	✓	✓	✓	✓
5	明德1F電梯旁		B-1			✓		✓	✓	✓	✓	✓	✓
6	明德1F車道旁		B-2			✓		✓	✓	✓	✓	✓	✓
7	快樂1F西後門		B-3			✓		✓	✓	✓	✓	✓	✓
8	1F廚房		B-4			✓		✓	✓	✓	✓	✓	✓
9	銀河班		C-1			✓		✓	✓	✓	✓	✓	✓
10	白雲班		C-2			✓		✓	✓	✓	✓	✓	✓
11	月亮班		C-3			✓		✓	✓	✓	✓	✓	✓
12	綠地班		C-4			✓		✓	✓	✓	✓	✓	✓
13	幼稚園健康中心		C-5			✓		✓	✓	✓	✓	✓	✓
14	快樂2F		C-6			✓		✓	✓	✓	✓	✓	✓
15	勤學1F西側樓梯		D-1			✓		✓	✓	✓	✓	✓	✓
16	勤學2F西側樓梯		D-2			✓		✓	✓	✓	✓	✓	✓
17	勤學3F西側樓梯		D-3			✓		✓	✓	✓	✓	✓	✓
18	勤學4F西側樓梯		D-4			✓		✓	✓	✓	✓	✓	✓
19	勤學1F東側樓梯		E-1			✓		✓	✓	✓	✓	✓	✓
20	勤學2F東側樓梯		E-2			✓		✓	✓	✓	✓	✓	✓
21	勤學3F東側樓梯		E-3			✓		✓	✓	✓	✓	✓	✓
22	勤學4F東側樓梯		E-4			✓		✓	✓	✓	✓	✓	✓
23	健康1F西側廁所		F-1			✓		✓	✓	✓	✓	✓	✓
24	健康2F西側廁所		F-2			✓		✓	✓	✓	✓	✓	✓
25	健康2F東側		F-3			✓		✓	✓	✓	✓	✓	✓
26	健康1F東側		F-4			✓		✓	✓	✓	✓	✓	✓
27	健康2F女廁		G-1			✓		✓	✓	✓	✓	✓	✓
28	健康3F女廁		G-2			✓		✓	✓	✓	✓	✓	✓
29	健康3F西側		G-3			✓		✓	✓	✓	✓	✓	✓
30	健康3F東側		G-4			✓		✓	✓	✓	✓	✓	✓
日期：109年10月5日													

機台巡檢數量：30 台

服務員：蔡有福

客戶簽章：事發關麗芬

五常國小飲水機維護紀錄表													
編號	安裝位置	型號	區別	濾心規格	濾心更換	機器巡檢	水質檢驗	加熱系統	冷卻系統	殺菌系統	外觀清潔	給排水系統	維護紀錄
1	明德2F會議室	UW-9615	A-1			✓		✓	✓	✓	✓	✓	✓
2	明德2F會計室	UW-9615	A-2			✓		✓	✓	✓	✓	✓	✓
3	明德3F圖書館	UW-9615	A-3			✓		✓	✓	✓	✓	✓	✓
4	活動中心5F	UR-313AS1	A-4			✓		✓	✓	✓	✓	✓	✓
5	明德1F電梯旁	UW-9615	B-1			✓		✓	✓	✓	✓	✓	✓
6	明德1F車道旁	UW-9615	B-2			✓		✓	✓	✓	✓	✓	✓
7	快樂1F西後門	UR-313AS1	B-3			✓		✓	✓	✓	✓	✓	✓
8	快樂1F廚房	UW-9615	B-4			✓		✓	✓	✓	✓	✓	✓
9	快樂2F	UW-9615	C-6			✓		✓	✓	✓	✓	✓	✓
10	銀河班	UW-9615	C-1			✓		✓	✓	✓	✓	✓	✓
11	彩虹班	UW-9615	C-2			✓		✓	✓	✓	✓	✓	✓
12	月亮班	UW-9615	C-3			✓		✓	✓	✓	✓	✓	✓
13	綠地班	UW-9203	C-4			✓		✓	✓	✓	✓	✓	✓
14	幼稚園健康中心	UW-20000A	C-5			✓		✓	✓	✓	✓	✓	✓
15	勤學1F西側樓梯	UW-9615	D-1			✓		✓	✓	✓	✓	✓	✓
16	勤學2F西側樓梯	UW-9615	D-2			✓		✓	✓	✓	✓	✓	✓
17	勤學3F西側樓梯	UW-9615	D-3			✓		✓	✓	✓	✓	✓	✓
18	勤學4F西側樓梯	UW-9615	D-4			✓		✓	✓	✓	✓	✓	✓
19	勤學1F東側樓梯	UW-9615	E-1			✓		✓	✓	✓	✓	✓	✓
20	勤學2F東側樓梯	UW-9615	E-2			✓		✓	✓	✓	✓	✓	✓
21	勤學3F東側樓梯	UW-9615	E-3			✓		✓	✓	✓	✓	✓	✓
22	勤學4F東側樓梯	UW-9615	E-4			✓		✓	✓	✓	✓	✓	✓
23	健康1F西側廁所	UW-998	F-1			✓		✓	✓	✓	✓	✓	✓
24	健康2F西側廁所	UW-9615	F-2			✓		✓	✓	✓	✓	✓	✓
25	健康2F東側	UW-9615	F-3			✓		✓	✓	✓	✓	✓	✓
26	健康1F東側	UW-9615	F-4			✓		✓	✓	✓	✓	✓	✓
27	健康2F女廁	UW-9615	G-1			✓		✓	✓	✓	✓	✓	✓
28	健康3F女廁	UR-313AS1	G-2			✓		✓	✓	✓	✓	✓	✓
29	健康3F西側	UR-313AS1	G-3			✓		✓	✓	✓	✓	✓	✓
30	健康3F東側	UR-313AS1	G-4			✓		✓	✓	✓	✓	✓	✓
日期：109年11月3日													

機台巡檢數量：30台

服務員：郭月陽

客戶簽章：李麗芬

五常國小飲水機維護紀錄表													
編號	安裝位置	型號	區別	濾心規格	濾心更換	機器巡檢	水質檢驗	加熱系統	冷卻系統	殺菌系統	外觀清潔	給排水系統	維護紀錄
1	明德2F會議室	UW-9615	A-1	UF-65	✓	✓	✓	✓	✓	✓	✓	✓	周秋奇
2	明德2F會計室	UW-9615	A-2	UF-65	✓	✓	✓	✓	✓	✓	✓	✓	周秋奇
3	明德3F圖書館	UW-9615	A-3	UF-65	✓	✓	✓	✓	✓	✓	✓	✓	周秋奇
4	活動中心5F	UR-313AS1	A-4	bl.64	✓	✓	✓	✓	✓	✓	✓	✓	周秋奇
5	明德1F電梯旁	UW-9615	B-1	UF-65	✓	✓	✓	✓	✓	✓	✓	✓	周秋奇
6	明德1F車道旁	UW-9615	B-2	UF-65	✓	✓	✓	✓	✓	✓	✓	✓	周秋奇
7	快樂1F西後門	UR-313AS1	B-3	bl.64	✓	✓	✓	✓	✓	✓	✓	✓	周秋奇
8	快樂1F廚房	UW-9615	B-4	UF-65	✓	✓	✓	✓	✓	✓	✓	✓	周秋奇
9	快樂2F	UW-9615	C-6	UF-65	✓	✓	✓	✓	✓	✓	✓	✓	周秋奇
10	銀河班	UW-9615	C-1	UF-65	✓	✓	✓	✓	✓	✓	✓	✓	周秋奇
11	彩虹班	UW-9615	C-2	UF-65	✓	✓	✓	✓	✓	✓	✓	✓	周秋奇
12	月亮班	UW-9615	C-3	UF-65	✓	✓	✓	✓	✓	✓	✓	✓	周秋奇
13	綠地班	UW-9203	C-4	bl.64	✓	✓	✓	✓	✓	✓	✓	✓	周秋奇
14	幼稚園健康中心	UW-20000A	C-5	bl.64	✓	✓	✓	✓	✓	✓	✓	✓	周秋奇
15	勤學1F西側樓梯	UW-9615	D-1	UF-65	✓	✓	✓	✓	✓	✓	✓	✓	周秋奇
16	勤學2F西側樓梯	UW-9615	D-2	UF-65	✓	✓	✓	✓	✓	✓	✓	✓	周秋奇
17	勤學3F西側樓梯	UW-9615	D-3	UF-65	✓	✓	✓	✓	✓	✓	✓	✓	周秋奇
18	勤學4F西側樓梯	UW-9615	D-4	UF-65	✓	✓	✓	✓	✓	✓	✓	✓	周秋奇
19	勤學1F東側樓梯	UW-9615	E-1	UF-65	✓	✓	✓	✓	✓	✓	✓	✓	周秋奇
20	勤學2F東側樓梯	UW-9615	E-2	UF-65	✓	✓	✓	✓	✓	✓	✓	✓	周秋奇
21	勤學3F東側樓梯	UW-9615	E-3	UF-65	✓	✓	✓	✓	✓	✓	✓	✓	周秋奇
22	勤學4F東側樓梯	UW-9615	E-4	UF-65	✓	✓	✓	✓	✓	✓	✓	✓	周秋奇
23	健康1F西側廁所	UW-998	F-1	bl.64	✓	✓	✓	✓	✓	✓	✓	✓	周秋奇
24	健康2F西側廁所	UW-9615	F-2	UF-65	✓	✓	✓	✓	✓	✓	✓	✓	周秋奇
25	健康2F東側	UW-9615	F-3	bl.64	✓	✓	✓	✓	✓	✓	✓	✓	周秋奇
26	健康1F東側	UW-9615	F-4	bl.64	✓	✓	✓	✓	✓	✓	✓	✓	周秋奇
27	健康2F女廁	UW-9615	G-1	bl.64	✓	✓	✓	✓	✓	✓	✓	✓	周秋奇
28	健康3F女廁	UR-313AS1	G-2	bl.64	✓	✓	✓	✓	✓	✓	✓	✓	周秋奇
29	健康3F西側	UR-313AS1	G-3	bl.64	✓	✓	✓	✓	✓	✓	✓	✓	周秋奇
30	健康3F東側	UR-313AS1	G-4	bl.64	✓	✓	✓	✓	✓	✓	✓	✓	周秋奇
日期：109年12月2日													周秋奇

機台巡檢數量：30 台

服務員：周秋奇

客戶簽章：王丹建