


五常國小飲水機維護紀錄表

編號	安裝位置	型號	區別	濾心規格	濾心更換	機器巡檢	水質檢驗	加熱系統	冷卻系統	殺菌系統	外觀清潔	給排水系統	維護紀錄
1	仁愛2F會議室	UR-313AS1	A-1			✓	✓	✓	✓	✓	✓	✓	✓
2	仁愛2F會計室	UR-313AS1	A-2			✓	✓	✓	✓	✓	✓	✓	✓
3	仁愛3F圖書館	UR-313AS1	A-3			✓	✓	✓	✓	✓	✓	✓	✓
4	活動中心5F	UR-313AS1	A-4			✓	✓	✓	✓	✓	✓	✓	✓
5	仁愛1F電梯旁	UR-313AS1	B-1			✓	✓	✓	✓	✓	✓	✓	✓
6	仁愛1F車道旁	UR-313AS1	B-2			✓	✓	✓	✓	✓	✓	✓	✓
7	和平1F西後門	UR-313AS1	B-3			✓	✓	✓	✓	✓	✓	✓	✓
8	1F廚房	UR-313AS1	B-4			✓	✓	✓	✓	✓	✓	✓	✓
9	彩虹班	UW-9213	C-1			✓	✓	✓	✓	✓	✓	✓	✓
10	藍天班	UW-9213	C-2			✓	✓	✓	✓	✓	✓	✓	✓
11	陽光班	UW-9213	C-3			✓	✓	✓	✓	✓	✓	✓	✓
12	綠地班	UW-9203	C-4			✓	✓	✓	✓	✓	✓	✓	✓
13	忠孝1F西側樓梯	UR-313AS1	D-1			✓	✓	✓	✓	✓	✓	✓	✓
14	忠孝2F西側樓梯	UR-313AS1	D-2			✓	✓	✓	✓	✓	✓	✓	✓
15	忠孝3F西側樓梯	UR-313AS1	D-3			✓	✓	✓	✓	✓	✓	✓	✓
16	忠孝4F西側樓梯	UR-313AS1	D-4			✓	✓	✓	✓	✓	✓	✓	✓
17	忠孝4F東側樓梯	UR-313AS1	E-1			✓	✓	✓	✓	✓	✓	✓	✓
18	忠孝2F東側樓梯	UR-313AS1	E-2			✓	✓	✓	✓	✓	✓	✓	✓
19	忠孝3F東側樓梯	UW-998	E-3			✓	✓	✓	✓	✓	✓	✓	✓
20	忠孝4F東側樓梯	UR-313AS1	E-4			✓	✓	✓	✓	✓	✓	✓	✓
21	信義1F西側廁所	UR-313AS1	F-1			✓	✓	✓	✓	✓	✓	✓	✓
22	信義2F西側	UR-313AS1	F-2			✓	✓	✓	✓	✓	✓	✓	✓
23	信義2F東側	UR-313AS1	F-3			✓	✓	✓	✓	✓	✓	✓	✓
24	信義1F東側	UR-313AS1	F-4			✓	✓	✓	✓	✓	✓	✓	✓
25	和平2F女廁	UR-313AS1	G-1			✓	✓	✓	✓	✓	✓	✓	✓
26	和平3F女廁	UR-313AS1	G-2			✓	✓	✓	✓	✓	✓	✓	✓
27	信義3F西側	UR-313AS1	G-3			✓	✓	✓	✓	✓	✓	✓	✓
28	信義3F東側	UR-313AS1	G-4			✓	✓	✓	✓	✓	✓	✓	✓
日期：106年10月2日													

機台巡檢數量：28 台

服務員：蔡中翰

客戶簽章：



五常國小飲水機維護紀錄表

編號	安裝位置	型號	區別	濾心規格	濾心更換	機器巡檢	水質檢驗	加熱系統	冷卻系統	殺菌系統	外觀清潔	給排水系統	維護紀錄
1	仁愛2F會議室	UR-313AS1	A-1			✓	✓	✓	✓	✓	✓	✓	✓
2	仁愛2F會計室	UR-313AS1	A-2			✓	✓	✓	✓	✓	✓	✓	✓
3	仁愛3F圖書館	UR-313AS1	A-3			✓	✓	✓	✓	✓	✓	✓	✓
4	活動中心5F	UR-313AS1	A-4			✓	✓	✓	✓	✓	✓	✓	✓
5	仁愛1F電梯旁	UR-313AS1	B-1			✓	✓	✓	✓	✓	✓	✓	✓
6	仁愛1F車道旁	UR-313AS1	B-2			✓	✓	✓	✓	✓	✓	✓	✓
7	和平1F西後門	UR-313AS1	B-3			✓	✓	✓	✓	✓	✓	✓	✓
8	1F廚房	UR-313AS1	B-4			✓	✓	✓	✓	✓	✓	✓	✓
9	彩虹班	UW-9213	C-1			✓	✓	✓	✓	✓	✓	✓	✓
10	藍天班	UW-9213	C-2			✓	✓	✓	✓	✓	✓	✓	✓
11	陽光班	UW-9213	C-3			✓	✓	✓	✓	✓	✓	✓	✓
12	綠地班	UW-9203	C-4			✓	✓	✓	✓	✓	✓	✓	✓
13	忠孝1F西側樓梯	UR-313AS1	D-1			✓	✓	✓	✓	✓	✓	✓	✓
14	忠孝2F西側樓梯	UR-313AS1	D-2			✓	✓	✓	✓	✓	✓	✓	✓
15	忠孝3F西側樓梯	UR-313AS1	D-3			✓	✓	✓	✓	✓	✓	✓	✓
16	忠孝4F西側樓梯	UR-313AS1	D-4			✓	✓	✓	✓	✓	✓	✓	✓
17	忠孝4F東側樓梯	UR-313AS1	E-1			✓	✓	✓	✓	✓	✓	✓	✓
18	忠孝2F東側樓梯	UR-313AS1	E-2			✓	✓	✓	✓	✓	✓	✓	✓
19	忠孝3F東側樓梯	UW-998	E-3			✓	✓	✓	✓	✓	✓	✓	✓
20	忠孝4F東側樓梯	UR-313AS1	E-4			✓	✓	✓	✓	✓	✓	✓	✓
21	信義1F西側廁所	UR-313AS1	F-1			✓	✓	✓	✓	✓	✓	✓	✓
22	信義2F西側	UR-313AS1	F-2			✓	✓	✓	✓	✓	✓	✓	✓
23	信義2F東側	UR-313AS1	F-3			✓	✓	✓	✓	✓	✓	✓	✓
24	信義1F東側	UR-313AS1	F-4			✓	✓	✓	✓	✓	✓	✓	✓
25	和平2F女廁	UR-313AS1	G-1			✓	✓	✓	✓	✓	✓	✓	✓
26	和平3F女廁	UR-313AS1	G-2			✓	✓	✓	✓	✓	✓	✓	✓
27	信義3F西側	UR-313AS1	G-3			✓	✓	✓	✓	✓	✓	✓	✓
28	信義3F東側	UR-313AS1	G-4			✓	✓	✓	✓	✓	✓	✓	✓
日期: 106年11月1日													

機台巡檢數量: 29 台

服務員:

張永煌

客戶簽章:

李麗芬

五常國小飲水機維護紀錄表

編號	安裝位置	型號	區別	濾心規格	濾心更換	機器巡檢	水質檢驗	加熱系統	冷卻系統	殺菌系統	外觀清潔	給排水系統	維護紀錄
1	仁愛2F會議室	UR-313AS1	A-1	UF6164	✓	✓	✓	✓	✓	✓	✓	✓	✓
2	仁愛2F會計室	UR-313AS1	A-2	UF6164	✓	✓	✓	✓	✓	✓	✓	✓	✓
3	仁愛3F圖書館	UR-313AS1	A-3	UF6164	✓	✓	✓	✓	✓	✓	✓	✓	✓
4	活動中心5F	UR-313AS1	A-4	UF6164	✓	✓	✓	✓	✓	✓	✓	✓	✓
5	仁愛1F電梯旁	UR-313AS1	B-1	UF6164	✓	✓	✓	✓	✓	✓	✓	✓	✓
6	仁愛1F車道旁	UR-313AS1	B-2	UF6164	✓	✓	✓	✓	✓	✓	✓	✓	✓
7	和平1F西後門	UR-313AS1	B-3	UF6164	✓	✓	✓	✓	✓	✓	✓	✓	✓
8	1F廚房	UR-313AS1	B-4	UF6164	✓	✓	✓	✓	✓	✓	✓	✓	✓
9	彩虹班	UW-9213	C-1	UF6164	✓	✓	✓	✓	✓	✓	✓	✓	✓
10	藍天班	UW-9213	C-2	UF6164	✓	✓	✓	✓	✓	✓	✓	✓	✓
11	陽光班	UW-9213	C-3	UF6164	✓	✓	✓	✓	✓	✓	✓	✓	✓
12	綠地班	UW-9203	C-4	UF6164	✓	✓	✓	✓	✓	✓	✓	✓	✓
13	忠孝1F西側樓梯	UR-313AS1	D-1	UF6164	✓	✓	✓	✓	✓	✓	✓	✓	✓
14	忠孝2F西側樓梯	UR-313AS1	D-2	UF6164	✓	✓	✓	✓	✓	✓	✓	✓	✓
15	忠孝3F西側樓梯	UR-313AS1	D-3	UF6164	✓	✓	✓	✓	✓	✓	✓	✓	✓
16	忠孝4F西側樓梯	UR-313AS1	D-4	UF6164	✓	✓	✓	✓	✓	✓	✓	✓	✓
17	忠孝4F東側樓梯	UR-313AS1	E-1	UF6164	✓	✓	✓	✓	✓	✓	✓	✓	✓
18	忠孝2F東側樓梯	UR-313AS1	E-2	UF6164	✓	✓	✓	✓	✓	✓	✓	✓	✓
19	忠孝3F東側樓梯	UW-998	E-3	UF6164	✓	✓	✓	✓	✓	✓	✓	✓	✓
20	忠孝4F東側樓梯	UR-313AS1	E-4	UF6164	✓	✓	✓	✓	✓	✓	✓	✓	✓
21	信義1F西側廁所	UR-313AS1	F-1	UF6164	✓	✓	✓	✓	✓	✓	✓	✓	✓
22	信義2F西側	UR-313AS1	F-2	UF6164	✓	✓	✓	✓	✓	✓	✓	✓	✓
23	信義2F東側	UR-313AS1	F-3	UF6164	✓	✓	✓	✓	✓	✓	✓	✓	✓
24	信義1F東側	UR-313AS1	F-4	UF6164	✓	✓	✓	✓	✓	✓	✓	✓	✓
25	和平2F女廁	UR-313AS1	G-1	UF6164	✓	✓	✓	✓	✓	✓	✓	✓	✓
26	和平3F女廁	UR-313AS1	G-2	UF6164	✓	✓	✓	✓	✓	✓	✓	✓	✓
27	信義3F西側	UR-313AS1	G-3	UF6164	✓	✓	✓	✓	✓	✓	✓	✓	✓
28	信義3F東側	UR-313AS1	G-4	UF6164	✓	✓	✓	✓	✓	✓	✓	✓	✓
日期：106年12月5日													

機台巡檢數量： 8 台

賀翠牌飲水機服務網
中山直營站
台北市新生北路1段112號
☎25219000分機700

服務員：

張承煜

客戶簽章：

事務長 關麗芬